

EUROGUIDE - MAKE MODEL YEAR GUIDELINES

The Euroguide is a document to help identify the right products needed for TPMS maintenance. There are three different coverage lists : a "Make\Model\Year Look up", a "Sensor Look Up" and a "Service Kits Look Up".

Make\Model\Year Look up: This list helps identify the right sensors needed using a Make/Model/Year classification.

1/ Choose the car manufacturer and the model of the car in the column " **Make Model**".

2/ Identify the code of the car in the second column " **Model code**".

3/ The columns " **Start of Application**" and " **End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.

4/ If the car falls within this time range, all the necessary information in the following columns can be found (same line, from left to the right)

5/ **Schrader Part Number**: This is the new After Market reference to order the matching sensor for the car.

6/ **OE Sensor reference**: This is car manufacturer's part number for the sensor.

7/ **Sensor Description**: This is the name and description of the sensor matching with the selected car.

8/ **Direct TPMS car park in Market**: number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

Notice: VDO and HUF are protected brands of the companies VDO and HUF. Schrader is a distributor of VDO and HUF products. Product design, description and brands are properties of HUF and VDO.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk.

This list will be regularly updated.

For further information: tpmseuroshop.com or aftermarket@schradereurope.co.uk

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Alfa Romeo							
159	939	2005-07	2011-11	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	354
4C	4C	2013-06	2021-03	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,170
8C Competizione	920	2006-12	2010-12	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	96
Brera	946	2005-11	2010-12	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	35
MiTo	955	2008-06	2013-07	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,114
MiTo	955	2013-08	2016-06	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1,010
MiTo (LCV)	955	2014-06	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3
Spider	946	2006-06	2010-12	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	35
Alpina							
Alpina 3	E90	2007-03	2009-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	107
Alpina 3	E90	2009-09	2012-12	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	30
Alpina 3	F30	2013-01	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	270
Alpina 3	F32	2013-04	2017-06	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	159
Alpina 4	F32	2014-03	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	55
Alpina 5	F10	2010-01	2017-10	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	194
Alpina 6	E63	2006-03	EOP	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3
Alpina 6	F06	2014-03	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2
Alpina 6	F12	2010-12	2018-10	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26
Alpina 7	F01	2010-09	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	16
Aston Martin							
Rapide	VH400	2010-01	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	92
V12 Zagato	Zagato	2012-09	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
V8 Vantage	AM305	2005-07	2014-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	801
Vanquish	AM310	2012-06	EOP	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	130
Virage	AM803	2011-05	2017-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
Audi							
A3 Sportback	AU370	2012-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,149
A3 Sportback (LCV)	AU370	2012-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A4	AU461/AU471	2001-01	2007-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,365
A4 (LCV)	AU481	2014-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11
A4 Allroad	AU486	2009-03	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	484
A4 Cabrio	AU465/AU475	2004-11	2009-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	672
A5	AU484	2006-12	2015-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	837
A5 Cabrio	AU485	2008-11	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,524
A5 Sportback	AU483	2009-07	2016-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,467
A5 Sportback (LCV)	AU483	2014-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A6	AU561	2004-03	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	673

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
A6	AU561	2009-06	2011-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	673
A6	AU571	2011-01	2017-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15,353
A6 (LCV)	AU571	2011-01	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A6 Allroad	AU566	2000-03	2006-05	4001	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	104
A6 Allroad	AU566	2006-05	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	182
A6 Allroad	AU566	2009-06	2011-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	193
A6 Allroad	AU572/4	2012-01	2019-09	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	625
A7	AU573	2010-09	2017-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	716
A8	AU631	1999-09	2010-12	4001	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	10,098
A8	AU641	2009-11	2016-09	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,512
Q3	AU316	2011-07	2018-03	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,993
Q3 (LCV)	AU316	2011-07	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Q5	AU416	2008-09	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,196
Q5 (LCV)	AU416	2008-09	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Q7	AU716	2005-09	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,365
Q7	AU716	2009-06	2014-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,165
Q7	AU726	2014-06	2021-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6
R8	AU714	2006-10	2009-06	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	672
R8	AU714	2009-06	2015-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,078
TT	AU334	2014-02	2020-10	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	789
Bentley							
Azure	BY824	2006-06	2010-01	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6
Azure	BY835	2013-10	2020-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32
Continental Flying Spur	BY611	2005-03	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	17
Continental Flying Spur	BY621	2012-12	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,051
Continental GT	BY624	2005-06	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	7,489
Continental GTC	BY615	2006-05	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,880
Continental GTC	BY625	2011-11	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,125
Mulsanne	BY831	2009-09	2018-04	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,488
BMW							
1-Series	F20	2011-07	2018-12	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	53,893
1-Series (LCV)	F20	2014-06	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	21
2-Series	F22	2013-11	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	14,566
2-Series Active Tourer	F45	2014-07	2021-06	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	5,502
3-Series	E46	1997-05	2004-12	4002	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	3,343
3-Series	F30	2011-11	2018-10	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	63,760
3-Series (LCV)	F30	2014-05	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3
3-Series GT	F34	2013-03	2020-01	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	11,262
4-Series	F32	2013-10	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	45,277
4-Series Gran Coupe	F36	2014-7	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	6,140
5-Series	F10	2010-01	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	46,950
5-Series	E39	1998-09	2003-07	4002	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,006
5-Series GT	F07	2009-09	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,415
6-Series	E63	2006-03	2010-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	668
6-Series	F12	2010-12	2018-10	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,952
6-Series Gran Coupe	F06	2012-03	2019-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,843
7-Series	F01	2014-06	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,388
i3	I01	2013-09	2020-04	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	10,186
i8	I12	2014-01	2020-04	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	674
X1	E84	2009-09	2014-02	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26,608
X3	F25	2010-09	2017-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	24,867
X3 (LCV)	F25	2014-06	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6
X4	F26	2014-04	2020-03	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	8,237
X5	E70	2006-10	2010-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	5,015
X5	E70	2010-03	2013-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	11,159
X5	F15	2013-07	2020-03	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	43,537
X5 (LCV)	F15	2014-06	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	8
X6	E71	2007-12	2011-10	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	668
Z4	E89	2010-09	2016-09	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,549
Z4	E89	2009-05	2010-08	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	33
Cadillac							
ATS	A1BL	2014-07	2018-06	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	9

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
ATS	A1SL	2012-07	2018-03	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	297
CTS	A1LL	2013-09	2018-03	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	175
CTS	GMX206	2008-01	EOP	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	97
CTS	GMX226	2010-06	EOP	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	227
CTS	GMX322	2006-01	2007-06	3055	25774007	Schrader Clamp-in Gen J 433MHz GM	416
Escalade	GMT926	2005-12	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,498
Escalade	GMT926	2014-03	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	160
Escalade	K2UL	2014-01	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	15
Escalade (LCV)	GMT926	2005-12	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	9
SRX	GMT166	2009-07	2015-12	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	2,609
SRX	GMT265	2005-06	2009-02	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	40
STS	GMX295	2005-06	2011-04	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	10
XLR	GMX215	2003-05	2009-04	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	9
XTS	P1LL	2012-05	2018-03	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Chevrolet							
Aveo	G1SC	2010-11	2016-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,429
Aveo	G1JC,G1SC	2014-03	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	5,074
Camaro	GMX521	2010-11	EOP	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	601
Captiva	C100	2006-06	2014-05	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	14,448
Captiva	C100		EOP	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	4,992
Cobalt	G1LC	2013-2	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	15,946
Corvette	GMX245	2004-07	2010-01	3053	25758221	Schrader Clamp-in Gen J 433MHz GM	1,698
Corvette	GMX245	2010-02	2013-01	3054	20925925	Schrader Clamp-in Gen J 433MHz GM	954
Cruze	D1JC	2014-06	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	2,114
Cruze	D1WC	2014-06	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	3,268
Express (PC)	GMT610	2002-07	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	V300	2010-07	2011-06	3049	20922901	Schrader Snap-in GEN4 type 433MHz GM	908
Malibu	V300	2011-07	2014-06	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	164
Malibu	V300	2014-07	2015-06	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	164
Matiz	M100	2014-06	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,764
Orlando	J309	2010-09	2017-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	5,904
Spark	M1JC	2009-07	2015-06	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	7,001
Suburban	GMT931	2006-03	2008-07	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	5
Trailblazer (LCV)	GMT360	2001-01	EOP	3055	25774007	Schrader Clamp-in Gen J 433MHz GM	4
Trax	G1UC	2012-03	2017-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	31,132
Volt	D1JCI	2010-11	2015-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,861
Chrysler							
300	LX	2011-01	2016-06	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	55
300C	LX	2014-06	EOP	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	22
Delta	844	2013-02	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	8
Grand Voyager	RT	2007-07	2011-01	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,882
Grand Voyager	RT	2011-01	2017-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1,985
Sebring	JS41C	2006-08	EOP	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	55
Sebring Convertible	JS27	2007-02	EOP	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	47
Citroen							
Berlingo	B9	2013-10	2017-01	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	7,701
Berlingo Multispace	B9	2013-10	2017-01	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	4,207
C4	B5	2004-11	2008-06	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	3,356
C4 Aircross	J4	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	662
C4 Aircross (LCV)	J4	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5
C4 Picasso	B58	2006-05	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	152,538
C5	X3/X40	2004-08	2007-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	105,385
C5	X40	2000-12	2004-07	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	80,550
C5	X7	2008-01	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	79,565
C5	X7	2013-09	2016-09	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	10,452
C5 (LCV)	X7	2007-10	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	14
C6	X6	2005-09	2012-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,678
C8	V3	2002-02	2005-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	13,425
C8	V3	2005-09	2014-06	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	12,677
C-Elysee	M3/M4	2012-10	2019-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	6,378
DS4	B75	2010-12	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	23,009
DS4	B75	2014-02	2017-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	8,292

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
DS4 (LCV)	B75	2010-12	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	18
DS5	B81	2011-06	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	14,461
DS5	B81	2014-02	2018-06	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	26,467
DS5 (LCV)	B81	2011-06	2014-01	3000	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	4
Jumper	X2/50	2006-01	2013-11	3000	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	1,801
Jumper	X2/50	2013-12	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,588
Jumpv	G9	2014-06	EOP	3001	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	1,153
Nemo	225	2007-10	2015-12	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	4,730
Nemo Multispace	225	2007-10	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	1,074
Dacia							
Dokker	K67	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	1,566
Dokker Van	F67	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	1,104
Duster	H79	2010-02	2017-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	84,195
Duster Pro	H79	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	97
Lodgy	J92	2012-01	2017-12	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	11,305
Lodgy (LCV)	J92	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	2
Logan	L52	2012-11	2019-12	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	16,132
Logan MCV	K52	2013-04	2020-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	15,893
Sandero	B52	2012-10	2019-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	65,406
Sandero Pro	B52	2012-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHZ Renault	17
Daewoo							
Gentra	J200	2013-8	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHZ GM	20,623
Nexia	T-CAR	2014-06	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHZ GM	17,021
Nexia	T	2014-03	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHZ GM	5,168
Dodge							
Avenger	JS41D	2006-11	2013-12	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	107
Caliber	PM49	2006-01	2011-12	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	304
Caravan	RT	2011-06	2017-05	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	25
Challenger	LC22	2008-01	2010-01	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	66
Challenger	LC22	2010-02	2017-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	168
Charger	LD	2010-12	2014-09	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	3
Charger	LD	2014-10	2016-06	3007	68241067AA	Schrader Snap-in GEN4 type 433MHZ Chrysler	3
Durango	WD75	2010-11	2016-12	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	332
Journey	JC49	2011-01	2014-06	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	559
Nitro	KA	2006-08	2011-12	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	209
Nitro (LCV)	KA	2006-08	2012-06	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	11
Ram	DS	2010-01	2012-12	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	3,955
Viper	ZD	2013-8	2015-06	3008	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	22
Ferrari							
California	F149	2008-07	2014-10	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHZ Fiat	3,607
Enzo	Enzo	2003-01	2004-12	4005	224551	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHZ Ferrari	109
F12	F152	2012-01	2018-03	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHZ Fiat	2,534
F430	F131	2004-09	2007-06	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHZ Fiat Group	35
F430	F131	2007-07	2009-12	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHZ Fiat	34
F458	F142	2009-09	2015-10	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHZ Fiat	7,686
F599 GTB	F141	2004-03	2012-06	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHZ Fiat Group	73
FF	F151	2011-06	2019-02	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHZ Fiat	1,156
Fiat							
500	312	2007-05	2015-07	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	56,710
500 (LCV)	312	2007-05	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	14
500C	312	2007-05	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	10,735
500L (LCV)	330	2014-06	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	1
Bravo	198	2007-01	2014-09	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHZ Fiat	933
Doblo	263	2009-12	2018-12	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	22,299
Doblo Combi	263	2014-06	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	59
Ducato	X2/50	2014-06	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHZ Chrysler/Fiat	474
Ducato	SEVEL X2	2014-06	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHZ Chrysler/Fiat	26
Ducato Combi	X2/50	2014-06	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHZ Chrysler/Fiat	179
Freemont	JF	2011-03	2014-06	3007	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	68,889
Freemont (LCV)	JF	2011-03	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	9
Idea	350	2003-09	2012-07	3017	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Fiat/GM	361
Linea	200	2007-03	2016-03	3016	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	12,787

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Punto	199	2005-09	2015-03	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	48,945
Qubo	225	2007-10	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	660
Scudo	G9	2006-09	2015-12	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	4,448
Scudo Combi	G9	2006-09	EOP	3001	9677130580	Schrader Snap-in GEN4 type 433MHz PSA HP	1,252
Sedici	YY2	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	164
Strada	178	1998-09	2015-12	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	453
Ulysse	V1	2001-01	2010-10	4031	9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	897
Ulysse	V1	2002-02	2005-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	1,801
Ford							
B-Max	B232	2014-06	2019-01	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	13,527
B-Max (LCV)	B232	2014-06	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	14
C-MAX	C344	2014-03	2016-12	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	39,700
C-Max (LCV)	C344	2010-08	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	69
Econoline	VN127	2006-01	EOP	3018	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	5
Ecosport	B515	2012-07	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,880
Escape	C520	2012-04	2017-06	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Escape	U377	2009-01	2012-04	3018	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	3
Explorer	U502	2010-11	2017-12	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,903
Fiesta	B299	2014-05	2015-12	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	83,585
Fiesta Van	B299	2014-06	2016-12	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	4,940
Focus	C346	2014-03	2017-06	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	113,934
Focus (LCV)	C346	2010-12	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	65
F-Series	P415	2008-09	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	24
Galaxy	CD340	2006-01	2014-12	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,965
Kuga	C520	2012-11	2019-09	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	42,190
Kuga (LCV)	C520	2012-11	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	15
Mondeo	CD345	2007-01	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	16,422
Mondeo	CD391	2014-10	2019-12	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	328
Mustang	S197	2004-09	2014-04	3024	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	212
Mustang	S550	2014-05	2020-10	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	43
S-MAX	CD340	2006-02	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	6,466
S-Max (LCV)	CD340	2006-02	EOP	4021	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	14
Tourneo Connect	V408	2014-03	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	3,384
Tourneo Courier	B460	2014-03	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	257
Tourneo Custom	V362	2013-04	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,287
Transit	V363	2013-06	2021-03	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	21,847
Transit Chassis	V363	2013-06	2021-03	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	18
Transit Combi	V348,V363	2013-06	2021-03	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Transit Combi	V363	2013-06	2021-03	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	561
Transit Connect	V408	2014-03	EOP	3021	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	18,667
Transit Courier	B460	2014-03	2014-09	3019	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	979
Transit Custom	V362	2013-04	EOP	3020	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	6,855
GMC							
Sierra	K2XG	2013-04	2019-06	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	10
Yukon	GMT922	2005-12	2013-12	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	275
Yukon	K2UG	2014-03	EOP	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Honda							
Accord	QE	2014-06	EOP	4072	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	1,138
Accord	2GB	2014-06	EOP	4072	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	3,155
Civic	2HC	2014-06	EOP	4064	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	31,090
Jazz	2AP,2HQ	2014-06	EOP	4064	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	19,507
Jazz	2WF	2014-9	EOP	4064	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	1,875
Hummer							
H3	GMT345	2005-03	2012-01	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	1
Hyundai							
Accent	RB	2014-03	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,798
Elantra	HD	2014-03	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10
Elantra	MD	2014-03	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	6,222
Equus	VI	2014-03	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	544
Genesis	DH	2014-01	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	886
Genesis Coupe	BK	2014-03	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	222
Grandeur	HG	2014-03	EOP	4061	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	208

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
i10	IA	2013-11	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	82,551
i10	IA,PA	2007-10	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	761
i10 (LCV)	PA	2014-03	EOP	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	6
i20	PB	2008-08	2014-06	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	19,502
i20	GB	2014-01	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	2,565
i20	GB,JB	2014-11	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	774
i20 (LCV)	GB	2014-11	EOP	3060	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	1
i30	FD	2007-10	2012-06	4026	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,745
i30	GD	2011-11	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	39,132
i30 (LCV)	GD	2011-10	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	6
i40	VF	2011-04	2014-03	4025	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	3,410
i40	VF	2014-04	EOP	4078	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	10,226
i40 (LCV)	VF	2011-04	2014-03	4025	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	3
ix20	JC	2010-09	2013-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	15,326
ix20	JC	2013-05	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	15,629
ix20 (LCV)	JC	2010-09	2013-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	6
ix35	LM	2014-03	EOP	4062	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,555
ix35 (LCV)	LM	2014-03	EOP	4062	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	12
Santa Fe	CM	2005-12	EOP	4057	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	13
Santa Fe	DM	2012-04	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	9,254
Santa Fe (LCV)	DM	2014-03	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	10
Solaris	RB	2014-03	EOP	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	87,315
Veloster	FS	2011-02	EOP	3056	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	1,843
Infiniti							
EX	P53B	2007-10	2016-03	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4,205
FX	P53C	2008-03	2014-08	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	10,450
FX	P53C	2014-09	2020-09	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	340
G	L53A	2006-08	2013-03	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,046
G	L53A	2013-04	2019-01	3039	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	108
M	L53E	2009-12	2016-09	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,502
Jaguar							
F-Type	X152	2014-03	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	4,523
XF	X250	2007-11	EOP	4023	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	26,608
XJ	X350	2005-10	EOP	4023	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	2,024
XK	X150	2006-01	EOP	4023	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	1,739
X-Type	X400	2007-01	EOP	4023	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	1,349
Jeep							
B-CUV	520	2014-10	EOP	4016	Info not available	Conti Snap-in TG1D 433MHz Chrysler	96
Cherokee	KK	2007-07	2012-12	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	561
Cherokee (LCV)	KL	2014-06	EOP	4068	Info not available	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	3
Compass	MK49	2006-05	2014-08	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	23,071
Grand Cherokee	WK74	2010-07	2015-06	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	53,685
Grand Cherokee	WH	2005-03	2010-06	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	5,671
Grand Cherokee (LCV)	WK74	2010-05	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	19
Patriot	MK74	2006-12	2014-08	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	417
Patriot (LCV)	MK74	2006-12	EOP	3005	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	35
Wrangler	JK72	2006-08	2010-09	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,840
Wrangler	JK72	2010-10	2013-12	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	26,167
Wrangler (LCV)	JK72	2006-08	EOP	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,724
Kia							
Cadenza	VG	2013-10	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	51
Carens	RP	2012-12	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	2,037
Ceed	JD	2012-03	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	43,836
Ceed (LCV)	JD	2014-03	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	5
Cerato	YD	2013-3	EOP	4063	52933-A7100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	11,670
New Carens	RP	2013-06	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	18
Optima	TF	2011-09	2013-08	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	2,777
Optima	TF	2013-08	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	2,508
Picanto	TA	2014-06	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	31,530
Picanto (LCV)	TA	2014-06	EOP	4059	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	11
Quoris	KH	2013-1	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	491
Rio	UB	2012-11	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	25,003

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Rio	QB	2000-01	EOP	4056	52933-3J000	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	86,591
Rio (LCV)	UB	2000-01	EOP	4053	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	26
Rio (LCV)	QB	2014-03	EOP	4052	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	6
Sorento	UM	2014-11	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	4
Sorento	XM	2009-05	2012-09	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	8,338
Sorento (LCV)	XM	2014-03	EOP	4060	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	18
Soul	PS	2013-11	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	10,838
Soul (LCV)	PS	2013-10	EOP	3059	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	7
Sportage	SL	2010-01	EOP	4062	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	53,183
Sportage (LCV)	SL	2014-03	EOP	4062	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	14
Venga (LCV)	YN	2010-02	2014-04	4027	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	9
Lamborghini							
Aventador	LB834	2011-05	2019-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	886
Gallardo	LB714	2007-01	2010-01	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	682
Gallardo	LB714	2010-02	2013-05	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	986
Gallardo	LB724	2013-06	2021-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	94
Murciélago	LB824	2011-01	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6
Lancia							
Delta	844	2008-04	EOP	4054	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	4,745
Flavia	JS27	2010-10	EOP	4015	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	1,943
Flavia	UF	2014-02	EOP	4016	Info not available	Conti Snap-in TG1D 433MHz Chrysler	203
Musa	848	2004-07	2012-11	3017	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	399
Thema	LX	2011-01	EOP	4031	9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	6,607
Voyager	RT	2007-07	2011-01	3006	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3,269
Voyager	RT,RU	2011-01	2015-10	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	397
Voyager (LCV)	RT	2011-01	EOP	3007	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	164
Land Rover							
Discovery (LCV)	L319	2004-07	2009-09	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	47
Freelander	L550	2014-07	EOP	4019	LR058023	Conti Clamp-in TG1C 433MHz Ford	46
Range Rover (LCV)	L322	2002-03	2003-02	4003	YDB 0000 60	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Land Rover	36
Range Rover (LCV)	L322	2005-01	2009-12	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	24
Range Rover Evoque	L538	2014-06	EOP	4023	LR031712	Conti Clamp-in TG1B 433MHz Ford	31,116
Range Rover Sport	L494	2014-06	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	1,775
Range Rover Sport (LCV)	L494	2014-06	EOP	4066	Unknown	Conti Clamp-in TG1C 433MHz JLR	12
Lexus							
C-CUV	600A	2014-11	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
CT	080A	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,484
ES	980L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,717
GS	920L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,169
GX	837L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	107
IS	030L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	967
IS	400A	2013-7	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,428
LF-A	973L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
LS	250L	2014-01	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	537
LX	220L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	159
NX	600A	2014-03	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,347
RX	640L	2014-06	EOP	4045	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	681
Lotus							
Elise	Monza	2008-01	EOP	3058	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	592
Evora	Eagle	2010-01	EOP	3058	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	323
Exige	Monza	2008-01	EOP	3058	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	491
Maserati							
Ghibli	M157	2013-11	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4,650
GranCabrio	M147	2009-09	2015-06	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	105
GranTurismo	M145	2014-01	2020-03	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	475
GT Coupe	M145	2007-04	2009-07	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	178
GT Coupe	M145	2009-07	2013-12	4009	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	497
Quattroporte	M139	2003-12	2012-10	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	718
Quattroporte	M156	2013-01	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	664
Maybach							
57/62	W240	2002-10	2012-12	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	59
Mazda							

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
2	J64F	2007-12	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	9,535
3	J68C	2009-07	2013-03	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	1,189
5	J74G	2010-07	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	3,491
6	J61A	2007-08	2012-08	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	396
6	J71E	2013-03	2018-09	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	16,883
6 (LCV)	J71E	2014-06	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	4
BT-50	J26E	2011-05	EOP	3020	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	7
CX-5	J53C	2011-11	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	31,180
CX-5 (LCV)	J53C	2011-11	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	7
CX-7	J31H	2009-06	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	178
CX-9	J50C	2010-08	EOP	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	124
MX-5	J04C	2010-03	2015-03	4028	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	2,599
Mercedes-Benz							
A-Class	W176	2013-01	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,384
A-Class	W176	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	38,169
A-Class (LCV)	W176	2014-06	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	41
B-Class	W246	2013-01	2018-07	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	36,859
B-Class (LCV)	W246	2014-12	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	18
C-Class	W204	2013-01	2013-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17,902
C-Class	W205	2014-01	2021-03	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	91,045
C-Class (LCV)	W205	2014-7	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1
C-Class Coupe	C204	2012-12	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	5,745
Citan	VS10	2012-09	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,623
Citan Combi	VS10	2014-01	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	355
CL	C216	2006-07	2014-03	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	129
CL	C217	2014-04	2020-06	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	480
CL	C215	1998-06	2006-02	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	200
CLA	C117	2012-12	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	322
CLA	C117	2014-12	2020-04	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	25,454
CLS	C218	2009-08	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,550
CLS	C218	2013-01	2017-10	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,285
CLS	C219	2004-09	2005-01	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	333
CLS	C219	2005-01	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	399
E-Class	C207	2014-06	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	14,023
E-Class	W212	2009-01	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	11,037
E-Class	W212	2013-01	2015-10	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	45,737
E-Class	W210	2001-11	2005-01	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	666
GLA	X156	2014-01	2014-11	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	49,279
GL-Class	X164	2006-01	2009-06	4040	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	66
GL-Class	X164	2009-06	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,270
GL-Class	X166	2013-01	EOP	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,011
GLK	X204	2012-12	2015-09	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	12,776
GLK (LCV)	X204	2014-06	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	21
G-Wagen	G463/461	2007-04	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,975
G-Wagen	G463/461	2013-01	2022-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,709
G-Wagen (LCV)	G463/461	2012-12	2022-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6
ML-Class	W166	2011-07	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	20,381
R-Class	V251	2005-06	2009-06	4040	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	499
R-Class	V251	2009-07	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,522
R-Class	V251	2013-01	2016-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	685
S-Class	W221	2005-05	2009-06	4040	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	3,330
S-Class	W221	2009-07	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,923
S-Class	W221	2013-01	2013-06	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	501
S-Class	W220	1998-05	2005-04	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	999
S-Class Coupe	C217	2014-7	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	596
S-Class Pullman	X222	2014-03	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4
SL	R230	2001-06	2005-05	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	999
SL	R230	2005-02	2009-07	4040	A 002 540 80 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	1,332
SL	R231	2009-08	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,017
SL	R231	2013-01	2014-05	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,377
SLK	R172	2013-01	2017-12	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	13,373
SLR	C199	2003-12	2007-06	4001	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	626

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
SLS	C197	2010-02	2012-12	3011	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,729
SLS	C197	2013-01	2016-03	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	623
Sprinter	NCV3	2014-06	EOP	3013	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	6,154
Sprinter Combi	NCV3	2013-01	2019-09	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,493
V-Class	W638	2014-06	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	23
Viano	VS20	2014-6	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	15
Viano (LCV)	VS20	2014-08	2023-07	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	178
Vito	VS20	2014-07	EOP	3012	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	320
Vito Combi	VS20	2012-12	2023-04	3011	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	194
Mini							
Clubman	R55	2007-08	2009-09	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	69
Clubman	R55	2009-08	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,076
Clubman (LCV)	R55	2014-06	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	9
Clubvan	R55	2012-07	2015-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	157
Countryman	R60	2010-08	2017-12	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	21,364
Countryman (LCV)	R60	2014-06	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3
Coupe	R58	2011-07	2015-08	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	972
Mini	F56	2013-12	2021-06	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	60,820
Mini	R56	2014-06	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	10,338
Mini (LCV)	F56	2014-01	EOP	4043	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	9
Paceman	R61	2012-11	2018-06	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,455
Roadster	R59	2011-12	2015-08	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,196
Mitsubishi							
ASX	ZC	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3,121
ASX (LCV)	ZC	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5
i-MiEV	TQ	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	489
L200	CR	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,153
L200	4P00,CR	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	93
Lancer	GS41	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,895
Outlander	GS45X	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10
Outlander	GS45X,RE	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	42
Outlander	RE	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3,363
Outlander (LCV)	RE	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3
Pajero	BK	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	686
Paiero (LCV)	BK	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	62
Spacestar	EL	2014-06	EOP	4073	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	9,369
Nissan							
370Z	C53D	2008-10	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,677
370Z	RC53D	2009-03	EOP	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	673
Almera	LB1A	2013-5	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	43,114
Alleon	F91G	2014-01	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	158
Cabstar	F91A	2014-06	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	260
Cabstar E	F91A	2014-06	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	81
C-Hatch	B12L	2014-10	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	2,580
GT-R	D52E	2007-09	2015-12	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,529
Juke	P12C	2010-05	2015-09	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	46,985
Juke (LCV)	P12C	2010-05	EOP	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	21
Leaf	B12G	2010-10	2017-09	4047	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	5,426
Micra	B02A	2010-03	2016-12	4077	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	25,154
Micra (LCV)	B02A	2010-03	EOP	4077	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	2
Murano	P42D	2007-10	2015-03	3038	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,018
Note	J02C	2013-08	2017-03	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	29,152
Note (LCV)	J02C	2012-03	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13
NV200	X11M	2014-04	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,050
NV200 Combi	X11M	2014-04	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	396
NV300	X82	2014-9	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	58
NV300 Combi	X82	2014-9	EOP	4030	(blank)	Conti Clamp-in TG1C 433MHz Nissan	10
Primera	ED	2001-12	2007-05	3037	40700 AV600	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,522
Qashqai	P32S	2013-12	2019-12	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	201,622
Qashqai (LCV)	P32S	2013-12	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	232
Sentra	L12F	2014-8	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	2,040
Teana	L42L	2014-01	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	7,126

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
X-Trail	P32R	2013-11	2019-12	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	17,548
X-Trail (LCV)	P32R	2013-11	EOP	4032	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	90
Opel							
Adam	GM 4403	2013-01	2014-07	3027	13581562	Schrader Snap-in GEN4 type 433MHz GM	452
Adam	GM 4403	2014-08	2015-08	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	22,337
Agila	H0310	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	742
Ampera	D1JOI	2011-09	2015-12	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	786
Antara	C105	2006-08	2010-11	3049	25789964	Schrader Snap-in GEN4 type 433MHz GM	775
Antara	C105	2010-11	2017-05	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	710
Astra	GM A3300	2004-01	2010-12	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3,229
Astra	GM P3400	2009-10	2011-09	3026	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,750
Astra	GM P3400	2011-09	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	14,937
Astra	GM P3400	2014-06	EOP	3033	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	127,481
Cascada	D1AO	2013-01	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,330
Combo	263	2014-06	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	820
Combo Combi	263	2014-06	EOP	3016	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	273
Corsa	GM 4530	2014-11	2015-02	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	1,005
Insignia	GM G3700	2008-10	2011-09	3026	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	32,292
Insignia	GM G3700	2011-09	2014-04	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	37,438
Meriva	GM S4470	2014-08	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	2,532
Meriva (LCV)	GM S4470	2014-06	EOP	3062	13581561	Schrader Snap-in GEN4 type 433MHz GM	24
Mokka	G1UO	2012-06	2015-08	3049	22853740	Schrader Snap-in GEN4 type 433MHz GM	52,383
Vectra	GM Z3200	2002-01	2008-09	3031	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	38,751
Vivaro	X82	2014-9	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	181
Vivaro Combi	X82	2014-9	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	44
Zafira	GM A3370	2009-01	2011-06	3031	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3,229
Zafira	GM A3370	2011-07	2016-09	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	19,483
Zafira (LCV)	GM A3370	2005-04	2008-12	3031	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13
Zafira Tourer	GM P3470	2011-09	2014-05	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	12,515
Zafira Tourer (LCV)	GM P3470	2011-09	EOP	3026	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2
Peugeot							
1007	A08	2014-03	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
207	A7	2005-11	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,777
207	A7	2013-09	2016-06	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	9,867
3008	T84	2008-11	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	201,196
3008	T84	2013-09	2016-09	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	81,911
3008 (LCV)	T84	2008-11	EOP	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	34
301	M3/M4	2012-10	2019-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	5,452
307	T5	2003-11	2006-12	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	94,727
307	T5	2007-01	2007-12	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	134,364
308	T7	2007-04	2013-08	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	147,786
308	T7	2013-09	2015-01	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	62,119
4008	J3	2014-06	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	1,834
4008 (LCV)	J3	2014-06	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	3
407	D2	2004-01	2006-02	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	268,729
408	T73	2014-06	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	3,823
5008	T87	2009-09	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHz PSA	107,793
5008	T87	2013-09	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	29,825
5008 (LCV)	T87	2009-09	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	20
508	W2	2010-11	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	97,327
508	W2	2013-09	2017-06	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	57,864
508 (LCV)	W2	2010-09	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	13
508 RXH	W24	2012-01	2013-09	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	45
508 RXH	W24	2013-09	2017-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHz PSA	318
607	Z8	1999-09	2004-10	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	16,795
607	Z8	2004-10	2009-03	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	11,420
807	V2	2002-02	2004-09	3004	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHz PSA	14,108
807	V2	2004-10	EOP	4031	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	15,628
Boxer	X2/50	2013-12	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4,326
Boxer Combi	X2/50	2013-12	EOP	3009	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	82
Expert	G9	2014-06	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	1,161
Expert Tepee	G9	2014-06	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	256

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
iOn	S3	2014-06	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	408
iOn (LCV)	S3	2014-06	EOP	4029	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	10
Partner	B9	2014-06	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,806
Partner Tepee	B9	2014-06	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	1,615
Partner Van	B9	2014-06	EOP	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	221
RCZ	T75	2009-12	2013-09	3000	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	16,031
RCZ	T75	2013-10	2016-12	3002	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	6,943
Porsche							
911	991	2011-09	2019-08	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	22,714
911	997	2004-06	2008-06	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,938
911	997	2008-07	2012-10	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,170
918 Spyder	918	2013-09	2014-12	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
Boxster	981	2012-03	2019-04	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,551
Boxster	987	2004-10	2008-10	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,615
Boxster	987	2008-07	2012-01	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,635
Cayenne	E2	2007-02	2010-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,228
Cayenne	E2	2010-04	2017-01	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32,494
Cayenne (LCV)	E2	2010-03	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11
Cayman	981	2013-05	2020-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,000
Cayman	987	2005-09	2008-12	4001	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	959
Cayman	987	2009-01	2013-04	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,706
Macan	PO416	2013-05	2020-07	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,307
Panamera	970	2009-09	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	13,409
Renault							
Captur	J87	2013-01	2019-10	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	66,500
Captur (LCV)	J87	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	40
Clio	X65	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,397
Clio	X85	2005-04	2014-05	3040	8200924614	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Renault	17,957
Clio	X98	2014-06	2018-12	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	74,458
Clio Van	X98	2012-07	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	12,392
Espace	J81	2002-07	2014-01	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	73,241
Espace (LCV)	J81	2002-07	EOP	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	4
Espace (LCV)	JFC	2014-07	EOP	4034	Info not available	Conti Snap-in TG1D 433MHz Renault	17
Fluence	L38	2009-10	2015-06	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	16,784
Grand Espace	J81	2002-07	EOP	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	4,168
Kangoo	X61	2007-10	2017-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,115
Kangoo	X61	2014-06	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,588
Kangoo Passenger	X61	2007-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10,218
Koleos	H45	2008-02	2013-12	3039	40700 1A70A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHZ Nissan	446
Laguna	X74	2000-12	2007-09	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	149,015
Laguna	X91	2007-10	2015-03	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	51,944
Laguna (LCV)	X91	2007-06	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	13
Laguna Coupe	D91	2008-07	2014-06	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	7,607
Latitude	L43	2010-09	2015-12	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	1,734
Master	X62	2009-11	2020-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	26,838
Master Passenger	X62	2009-11	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	873
Megane	B32	2009-11	2015-12	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	113
Megane	B32,X95	2011-05	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,186
Megane	X64	1997-01	2002-10	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	11,921
Megane	X84	2002-11	2008-10	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	59,606
Megane	X95	2008-11	2015-09	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	95,976
Megane Van	X84	2014-03	EOP	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	5
Megane Van	X95	2014-06	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,308
Modus	J77	2004-05	2012-12	3040	8200924614	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Renault	2,980
Scenic	J95	2003-06	2007-10	4036	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	71,527
Scenic	J95	2009-01	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	57,513
Scenic	J64	1997-01	2003-06	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	11,921
Scenic (LCV)	J95	2009-02	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	38
Symbol/Thalia	L52	2013-04	2020-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,034
Trafic	X82	2014-03	2026-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	26,556
Trafic Passenger	X82	2014-03	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,160
Twingo	X07	2014-03	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	34,182

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Twingo	X44	2007-01	2016-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	18,278
Twingo Van	X07	2014-10	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	257
Vel Satis	X73	2001-09	2009-11	3042	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	147,056
Zoe	X10	2012-09	2019-03	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,471
Zoe (LCV)	X10	2013-06	EOP	4035	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3
Rolls-Royce							
Ghost	RR04	2009-12	2019-11	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	88
Phantom	RR01	2003-02	2016-09	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	18
Phantom	RR01	2007-09	2011-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	124
Phantom Coupe	RR02	2014-06	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	12
Phantom Drophead Coupe	RR02	2007-04	2011-12	4007	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	124
Phantom Drophead Coupe	RR02	2012-01	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	138
Wraith	RR04	2013-8	EOP	4010	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	401
Skoda							
Citigo	SK120	2011-10	2018-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,560
Fabia	SK250	2014-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,909
Fabia	SK260	2013-11	2019-04	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	480
Fabia Van	SK250	2014-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33
Fabia Van	SK260	2013-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Octavia	SK371	2012-11	2019-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,761
Octavia (LCV)	SK371	2012-11	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Rapid	SK251/1	2012-09	2020-04	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,712
Rapid Spaceback	SK253/1	2013-10	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,784
Roomster (LCV)	SK258	2006-04	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
Yeti	SK316	2009-06	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,051
Yeti (LCV)	SK316	2009-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Smart							
forfour	A453	2014-07	2020-09	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,888
Fortwo	A452	2014-04	2021-03	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,766
Fortwo (LCV)	C453	2014-8	EOP	3041	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	5
Ssangyong							
Korando	C200/AS11	2013-08	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	5
Korando C	C200/AS11	2013-08	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	437
Korando C (LCV)	C200/AS11	2013-08	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2
Korando Sports	Q150	2014-11	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14
Nomad	Q150	2014-2	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	45
Rexton	Y200	2014-05	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	199
Rexton (LCV)	Y200	2014-05	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	17
Rexton SC	Y200	2014-05	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1
Rodius	A100	2014-05	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	169
Rodius (LCV)	A100	2014-05	EOP	3068	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1
Subaru							
BRZ	E88	2014-01	EOP	4045	28103-CA101	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	750
C-Concept	VL9	2014-6	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	4,250
Forester	FM5	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,361
Forester (LCV)	FM5	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	13
Impreza	MF1	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	3,011
Impreza	ZR1	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	165
Impreza (LCV)	MF1	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
Justy	D71A	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	04AL	2014-10	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	262
Legacy	EZ5	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,553
Outback	04AL	2014-11	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25
Outback	BF4	2014-9	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	472
Outback	EZ5	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	3,832
Trezia	217A	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	604
Tribeca	00X	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5
XV	MF1	2014-01	EOP	3064	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,411
Suzuki							
Alto	YC5	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	14,865
Alto Van	YC5	2014-03	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1
Jimny	YR7	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	576

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Jimny	YR6,YR7	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	83
Jimny (LCV)	YR7	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	40
Splash	YV1	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	781
Splash	YV4	2013-9	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,269
Splash	YV1,YV4	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2
Swift	YP6	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	7,691
Swift	YP6,YP7	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	21,259
Swift (LCV)	YP6	2014-06	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	7
SX4	YY1,YY3	2013-08	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	784
SX4 S-Cross	YAA	2013-11	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	48,952
SX4 S-Cross (LCV)	YAA	2013-11	EOP	4065	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	38
Tesla							
Model S	Model S	2013-5	EOP	4058		Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	9,623
Toyota							
Alphard	480L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18
Auris	130A	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	78,919
Auris	130L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Auris (LCV)	130A	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13
Avalon	770N	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Avenis	312N	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Avenis	445L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18,243
Avenis (LCV)	445L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Camry	050A	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,378
Camry	045L	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Corolla	140A	2014-01	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	199
Corolla	366A	2013-9	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	49,545
Corolla	150A	2014-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	139
Corolla	150L,252L	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	368
Corolla	466A	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,569
Dyna	U300-500	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	U600/C600	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	82
Dyna	Dutro(2)	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Dyna	131N	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	609
GT 86	E88	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,094
Hiace	550N	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	36
Highlander	440A	2014-10	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	35
Highlander	397L	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	669L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,785
IQ	630L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,265
Land Cruiser	215L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,091
Land Cruiser	611L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	112
Land Cruiser (LCV)	215L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	120
Land Cruiser Prado	611L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	957
Land Cruiser V8	215L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	45
Prius	590L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,273
Prius (LCV)	590L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius Plus	030A	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	405
Proace	G9	2014-06	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	361
Proace Combi	G9	2014-06	EOP	3003	9808859080	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	9
RAV4	410A	2013-01	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	9,837
RAV4 (LCV)	120L	2005-11	2012-12	4044	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	230
Sienna	580L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10
Tundra	180L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Tundra	480A/180L	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
Urban Cruiser	260L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	396
Venza	470L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	285
Verso	151L,595L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	21
Verso	595L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,073
Verso (LCV)	595L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37
Verso-S	770L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,008
Verso-S (LCV)	770L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Yaris	020L	2014-03	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2

Make Model	Car Model Code	Start of Application	End of Application	Schrader Part Number (NEW)	OE sensor reference	Sensor Description	Direct TPMS car park in Market in 2014
Yaris	850L	2014-06	EOP	4045	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	98,805
Volkswagen							
Amarok	VN817	2009-11	2017-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,727
Caravelle	VN750	2003-12	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,982
Crafter	VN830	2006-04	2017-09	4038	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	4,777
Crafter Combi	VN830	2014-06	EOP	4038	A 002 540 95 17	Conti Clamp-in TG1B no RF link Siemens VDO 433MHz Daimler	21
Eos	VW465	2006-02	2015-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	477
Golf	VW360	2014-05	2016-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,280
Golf	VW370	2012-08	2018-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	61,432
Golf (LCV)	VW370	2012-08	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29
Golf Plus	VW379	2014-02	2019-01	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,167
Golf Plus (LCV)	VW379	2014-02	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
Golf Sportsvan	VW379	2014-3	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	841
Golf Sportsvan (LCV)	VW379	2014-4	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Golf SV	VW379	2014-03	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	168
Jetta	VW361	2010-07	2016-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,848
New Beetle	VW314	2006-01	2010-07	4037	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,934
New Beetle	VW324	2011-08	2017-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,158
New Beetle Convertible	VW325	2012-09	2017-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,716
Passat	VW451	2005-03	2010-11	4037	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	22,570
Passat	VW471	2010-12	2013-09	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	13,346
Passat	VW471	2013-09	2014-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,334
Passat CC	VW464	2008-03	2014-09	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	540
Passat CC	VW464	2014-09	2015-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,181
Phaeton	VW611	2001-12	2007-06	4001	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	2,579
Phaeton	VW611	2007-06	2010-01	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,577
Phaeton	VW611	2010-01	2016-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,925
Scirocco	VW364	2008-06	2016-06	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,374
Scirocco (LCV)	VW364	2008-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Sharan	VW428	2010-06	2017-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,181
Sharan (LCV)	VW428	2010-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Tiguan	VW316	2007-08	2014-02	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	13,456
Tiguan	VW316	2014-02	2014-12	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,139
Tiguan (LCV)	VW316	2007-08	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	7
Touareg	VW516	2002-10	2007-01	4005	7L0 907 275 B	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	3,869
Touareg	VW516	2007-01	2010-03	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,869
Touareg	VW526	2010-03	2014-02	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,120
Touareg	VW526	2014-03	2017-09	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,106
Touareg (LCV)	VW526	2010-03	EOP	4009	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
Touran (LCV)	VW368	2010-07	EOP	4011	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	26
Transporter	VN750	2003-03	2017-03	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,754
Transporter Shuttle	VN750	2014-06	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Up!	VW120	2011-08	2018-07	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,323
Up! (LCV)	VW120	2011-08	EOP	4012	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Volvo							
C30	Y279	2006-09	2012-12	4041	31302096	Conti Clamp-in TG1C 433MHz Volvo	257
V40	Y555	2014-03	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	50,018
V40 (LCV)	Y555	2014-07	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	10
V40 XC	Y555	2014-03	EOP	4070	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,052
V50	Y280	2003-11	2012-05	4041	31302096	Conti Clamp-in TG1C 433MHz Volvo	360
V60	Y352	2010-09	2014-06	4041	31302096	Conti Clamp-in TG1C 433MHz Volvo	327
V70	Y285	2007-05	2008-10	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	326
V70	Y285	2008-01	2014-06	4042	31302097	Conti Clamp-in TG1C 433MHz Volvo	318
XC60	Y413	2008-05	2014-06	4041	31302096	Conti Clamp-in TG1C 433MHz Volvo	459
XC70	Y381	2007-02	2014-06	4041	31302096	Conti Clamp-in TG1C 433MHz Volvo	268
XC70	Y381	2007-05	2008-10	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	326
XC90	Y289	2002-04	2014-12	3046	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	869

Euroguide -Sensors Look Up

Sensors Look Up: This list identifies which cars can be fitted with a particular Schrader referenced part number.

- 1/ Identify the Schrader Code of the sensor (After Market reference) in the first column "**Schrader Part Number**"
- 2/ In the same column identify which car manufacturer and car model the sensor is fitted on.
-- When the sensor reference is matching the right car model, all the necessary information concerning the car and the sensor are in the following columns (same line, from left to the right).
- 3/ **Car Model Code** is the Identification code of the vehicle.
- 4/ "**Start of Application**" and "**End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.
- 5/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.
- 6/ **Sensor Description:** Description of the After Market reference.
- 7/ **Direct TPMS car park in Market:** number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk.
This list will be regularly updated.
For further information: tpmseuroshop.com or aftermarket@schradet.co.uk

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
3000						
Citroen						
C4 Picasso	B58	2006-05	2013-09	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	152,538
DS4	B75	2010-12	2014-01	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	23,009
DS4 (LCV)	B75	2010-12	2014-01	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	18
DS5	B81	2011-06	2014-01	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	14,461
DS5 (LCV)	B81	2011-06	2014-01	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	4
Jumper	X2/50	2006-01	2013-11	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	1,801
Peugeot						
3008	T84	2008-11	2013-09	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	201,196
3008 (LCV)	T84	2008-11	EOP	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	34
307	T5	2007-01	2007-12	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	134,364
308	T7	2007-04	2013-08	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	147,786
5008	T87	2009-09	2013-09	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	107,793
RCZ	T75	2009-12	2013-09	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	16,031
3001						
Citroen						
Jumpy	G9	2014-06	EOP	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	1,153
Fiat						
Scudo Combi	G9	2006-09	EOP	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	1,252
3002						
Citroen						
Berlingo	B9	2013-10	2017-01	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	7,701
Berlingo Multispace	B9	2013-10	2017-01	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	4,207
C5	X7	2013-09	2016-09	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	10,452
C5 (LCV)	X7	2007-10	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	14
C-Elysee	M3/M4	2012-10	2019-12	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	6,378
DS4	B75	2014-02	2017-12	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	8,292
DS5	B81	2014-02	2018-06	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	26,467
Jumper	X2/50	2013-12	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,588

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Peugeot						
207	A7	2013-09	2016-06	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	9,867
3008	T84	2013-09	2016-09	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	81,911
301	M3/M4	2012-10	2019-12	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	5,452
308	T7	2013-09	2015-01	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	62,119
408	T73	2014-06	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,823
5008	T87	2013-09	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	29,825
5008 (LCV)	T87	2009-09	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	20
508	W2	2013-09	2017-06	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	57,864
508 (LCV)	W2	2010-09	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	13
508 RXH	W24	2013-09	2017-12	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	318
Partner	B9	2014-06	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	3,806
Partner Tepee	B9	2014-06	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	1,615
Partner Van	B9	2014-06	EOP	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	221
RCZ	T75	2013-10	2016-12	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	6,943
3003						
Fiat						
Scudo	G9	2006-09	2015-12	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	4,448
Peugeot						
Expert	G9	2014-06	EOP	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	1,161
Expert Tepee	G9	2014-06	EOP	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	256
Toyota						
Proace	G9	2014-06	EOP	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	361
Proace Combi	G9	2014-06	EOP	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	9
3004						
Citroen						
C5	X40	2000-12	2004-07	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	80,550
C8	V3	2002-02	2005-10	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	13,425
Fiat						
Ulysse	V1	2002-02	2005-10	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	1,801
Peugeot						
607	Z8	1999-09	2004-10	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	16,795
807	V2	2002-02	2004-09	543002	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA	14,108
3005						
Jeep						
Compass	MK49	2006-05	2014-08	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	23,071
Patriot	MK74	2006-12	2014-08	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	417
Patriot (LCV)	MK74	2006-12	EOP	56029481AB	Schrader Snap-in GEN4 type 433MHz Chrysler	35
3006						
Chrysler						
Grand Voyager	RT	2007-07	2011-01	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	1,882
Sebring	JS41C	2006-08	EOP	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	55
Sebring Convertible	JS27	2007-02	EOP	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	47
Dodge						
Avenger	JS41D	2006-11	2013-12	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	107
Caliber	PM49	2006-01	2011-12	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	304

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Challenger	LC22	2008-01	2010-01	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	66
Nitro	KA	2006-08	2011-12	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	209
Nitro (LCV)	KA	2006-08	2012-06	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	11
Jeep						
Cherokee	KK	2007-07	2012-12	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	561
Grand Cherokee	WH	2005-03	2010-06	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	5,671
Wrangler	JK72	2006-08	2010-09	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,840
Wrangler (LCV)	JK72	2006-08	EOP	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	2,724
Lancia						
Voyager	RT	2007-07	2011-01	56029539AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3,269
3007						
Chrysler						
Grand Voyager	RT	2011-01	2017-09	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	1,985
Dodge						
Caravan	RT	2011-06	2017-05	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	25
Challenger	LC22	2010-02	2017-09	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	168
Charger	LD	2010-12	2014-09	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Charger		2014-10	2016-06	68241067AA	Schrader Snap-in GEN4 type 433MHz Chrysler	3
Durango	WD75	2010-11	2016-12	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	332
Journey	JC49	2011-01	2014-06	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	559
Ram	DS	2010-01	2012-12	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	3,955
Fiat						
Freemont	JF	2011-03	2014-06	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	68,889
Jeep						
Grand Cherokee	WK74	2010-07	2015-06	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	53,685
Grand Cherokee (LCV)	WK74	2010-05	EOP	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	19
Wrangler	JK72	2010-10	2013-12	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	26,167
Lancia						
Voyager	RT,RU	2011-01	2015-10	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	397
Voyager (LCV)	RT	2011-01	EOP	56029398AB	Schrader Snap-in GEN4 type 433MHz Chrysler	164
3008						
Chrysler						
300	LX	2011-01	2016-06	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	55
300C	LX	2014-06	EOP	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	22
Dodge						
Viper	ZD	2013-8	2015-06	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	22
3009						
Alfa Romeo						
4C	4C	2013-06	2021-03	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,170
Fiat						
Ducato	SEVEL X2	2014-06	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	26
Ducato	X2/50	2014-06	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	474
Ducato Combi	X2/50	2014-06	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	179
Maserati						
Ghibli	M157	2013-11	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4,650
GranTurismo	M145	2014-01	2020-03	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	475

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Quattroporte	M156	2013-01	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	664
Peugeot						
Boxer	X2/50	2013-12	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	4,326
Boxer Combi	X2/50	2013-12	EOP	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	82
3011						
Mercedes-Benz						
A-Class	W176	2013-01	2014-11	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,384
B-Class	W246	2013-01	2018-07	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	36,859
C-Class	W204	2013-01	2013-12	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17,902
C-Class Coupe	C204	2012-12	EOP	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	5,745
CL	C216	2006-07	2014-03	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	129
CL	C217	2014-04	2020-06	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	480
CLA	C117	2012-12	2014-11	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	322
CLS	C218	2009-08	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,550
CLS		2013-01	2017-10	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	7,285
E-Class	W212	2009-01	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	11,037
E-Class		2013-01	2015-10	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	45,737
GLA	X156	2014-01	2014-11	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	49,279
GL-Class	X164	2009-06	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,270
GL-Class	X166	2013-01	EOP	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,011
GLK	X204	2012-12	2015-09	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	12,776
G-Wagen	G463/461	2007-04	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,975
G-Wagen		2013-01	2022-12	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,709
G-Wagen (LCV)	G463/461	2012-12	2022-12	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6
ML-Class	W166	2011-07	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	20,381
R-Class	V251	2009-07	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,522
R-Class		2013-01	2016-12	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	685
S-Class	W221	2009-07	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,923
S-Class		2013-01	2013-06	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	501
SL	R231	2009-08	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,017
SL		2013-01	2014-05	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,377
SLK	R172	2013-01	2017-12	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	13,373
SLS	C197	2010-02	2012-12	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,729
SLS		2013-01	2016-03	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	623
Sprinter Combi	NCV3	2013-01	2019-09	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,493
Vito Combi	VS20	2012-12	2023-04	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	194
3012						
Mercedes-Benz						
V-Class	W638	2014-06	EOP	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	23
Viano	VS20	2014-6	EOP	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	15
Viano (LCV)	VS20	2014-08	2023-07	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	178
Vito	VS20	2014-07	EOP	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	320
3013						
Mercedes-Benz						
A-Class	W176	2014-12	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	38,169
A-Class (LCV)	W176	2014-06	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	41

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
B-Class (LCV)	W246	2014-12	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	18
C-Class	W205	2014-01	2021-03	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	91,045
C-Class (LCV)	W205	2014-7	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	1
CLA	C117	2014-12	2020-04	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	25,454
E-Class	C207	2014-06	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	14,023
GLK (LCV)	X204	2014-06	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	21
S-Class Coupe	C217	2014-7	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	596
S-Class Pullman	X222	2014-03	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4
Sprinter	NCV3	2014-06	EOP	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	6,154
3016						
Alfa Romeo						
MiTo	955	2013-08	2016-06	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1,010
MiTo (LCV)	955	2014-06	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	3
Citroen						
Nemo	225	2007-10	2015-12	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	4,730
Nemo Multispace	225	2007-10	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1,074
Fiat						
500	312	2007-05	2015-07	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	56,710
500 (LCV)	312	2007-05	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	14
500C	312	2007-05	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	10,735
500L (LCV)	330	2014-06	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	1
Doblo	263	2009-12	2018-12	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	22,299
Doblo Combi	263	2014-06	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	59
Freemont (LCV)	JF	2011-03	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	9
Linea	200	2007-03	2016-03	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	12,787
Qubo	225	2007-10	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	660
Strada	178	1998-09	2015-12	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	453
Opel						
Combo	263	2014-06	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	820
Combo Combi	263	2014-06	EOP	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	273
3017						
Fiat						
Idea	350	2003-09	2012-07	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	361
Lancia						
Musa	848	2004-07	2012-11	51750439	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	399
3018						
Ford						
Econoline	VN127	2006-01	EOP	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	5
Escape	U377	2009-01	2012-04	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	3
3019						
Ford						
Ecosport	B515	2012-07	2014-09	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,880
Tourneo Courier	B460	2014-03	2014-09	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	257
Transit Courier	B460	2014-03	2014-09	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	979
3020						
Ford						

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Escape	C520	2012-04	2017-06	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Explorer	U502	2010-11	2017-12	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,903
F-Series	P415	2008-09	EOP	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	24
Tourneo Custom	V362	2013-04	EOP	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	1,287
Transit	V363	2013-06	2021-03	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	21,847
Transit Chassis	V363	2013-06	2021-03	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	18
Transit Combi	V348,V363	2013-06	2021-03	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
Transit Combi	V363	2013-06	2021-03	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	561
Transit Custom	V362	2013-04	EOP	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	6,855
Mazda						
BT-50	J26E	2011-05	EOP	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	7
3021 Ford						
B-Max	B232	2014-06	2019-01	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	13,527
B-Max (LCV)	B232	2014-06	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	14
C-MAX	C344	2014-03	2016-12	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	39,700
C-Max (LCV)	C344	2010-08	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	69
Fiesta	B299	2014-05	2015-12	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	83,585
Fiesta Van	B299	2014-06	2016-12	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	4,940
Focus	C346	2014-03	2017-06	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	113,934
Focus (LCV)	C346	2010-12	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	65
Kuga	C520	2012-11	2019-09	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	42,190
Kuga (LCV)	C520	2012-11	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	15
Mondeo	CD391	2014-10	2019-12	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	328
Mustang	S550	2014-05	2020-10	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	43
Tourneo Connect	V408	2014-03	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	3,384
Transit Connect	V408	2014-03	EOP	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	18,667
3024 Ford						
Mustang	S197	2004-09	2014-04	DR3V-1A180-BA	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	212
3026 Chevrolet						
Volt	D1JCI	2010-11	2015-05	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,861
Opel						
Ampera	D1JOI	2011-09	2015-12	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	786
Astra	GM P3400	2009-10	2011-09	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,750
Astra		2011-09	2014-05	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	14,937
Cascada	D1AO	2013-01	2014-05	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,330
Insignia	GM G3700	2008-10	2011-09	13327259	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	32,292
Insignia		2011-09	2014-04	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	37,438
Zafira Tourer	GM P3470	2011-09	2014-05	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	12,515
Zafira Tourer (LCV)	GM P3470	2011-09	EOP	13348393	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	2
3027 Opel						
Adam	GM 4403	2013-01	2014-07	13581562	Schrader Snap-in GEN4 type 433MHz GM	452
3031						

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Opel						
Astra	GM A3300	2004-01	2010-12	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3,229
Vectra	GM Z3200	2002-01	2008-09	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	38,751
Zafira	GM A3370	2009-01	2011-06	13172567	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	3,229
Zafira		2011-07	2016-09	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	19,483
Zafira (LCV)	GM A3370	2005-04	2008-12	13354312	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13
3033						
Opel						
Astra	GM P3400	2014-06	EOP	13581560	Schrader Clamp-in Gen Gamma 433MHz GM	127,481
3037						
Nissan						
Primera	ED	2001-12	2007-05	40700 AV600	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Nissan	1,522
3038						
Infiniti						
M	L53E	2009-12	2016-09	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,502
Nissan						
370Z	C53D	2008-10	EOP	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,677
370Z	RC53D	2009-03	EOP	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	673
GT-R	D52E	2007-09	2015-12	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	3,529
Murano	P42D	2007-10	2015-03	40700 JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,018
3039						
Infiniti						
EX	P53B	2007-10	2016-03	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4,205
FX	P53C	2008-03	2014-08	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	10,450
FX		2014-09	2020-09	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	340
G	L53A	2006-08	2013-03	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,046
G		2013-04	2019-01	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	108
Renault						
Koleos	H45	2008-02	2013-12	40700 1AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	446
3040						
Renault						
Clio	X85	2005-04	2014-05	8200924614	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	17,957
Modus	J77	2004-05	2012-12	8200924614	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	2,980
3041						
Dacia						
Dokker	K67	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,566
Dokker Van	F67	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,104
Duster	H79	2010-02	2017-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	84,195
Duster Pro	H79	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	97
Lodgy	J92	2012-01	2017-12	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	11,305
Lodgy (LCV)	J92	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	2
Logan	L52	2012-11	2019-12	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	16,132
Logan MCV	K52	2013-04	2020-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	15,893
Sandero	B52	2012-10	2019-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	65,406
Sandero Pro	B52	2012-10	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	17
Mercedes-Benz						

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Citan	VS10	2012-09	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,623
Citan Combi	VS10	2014-01	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	355
Opel						
Vivaro	X82	2014-9	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	181
Vivaro Combi	X82	2014-9	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	44
Renault						
Captur	J87	2013-01	2019-10	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	66,500
Captur (LCV)	J87	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	40
Clio	X65	2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,397
Clio	X98	2014-06	2018-12	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	74,458
Clio Van	X98	2012-07	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	12,392
Kangoo	X61	2007-10	2017-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,115
Kangoo		2014-06	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,588
Kangoo Passenger	X61	2007-10	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	10,218
Master	X62	2009-11	2020-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	26,838
Master Passenger	X62	2009-11	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	873
Symbol/Thalia	L52	2013-04	2020-03	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,034
Trafic	X82	2014-03	2026-03	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	26,556
Trafic Passenger	X82	2014-03	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,160
Twingo	X07	2014-03	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	34,182
Twingo	X44	2007-01	2016-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	18,278
Twingo Van	X07	2014-10	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	257
Smart						
forfour	A453	2014-07	2020-09	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,888
Fortwo	A452	2014-04	2021-03	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,766
Fortwo (LCV)	C453	2014-8	EOP	407001628R	Schrader Snap-in HS with 20deg angle 433MHz Renault	5
3042						
Renault						
Espace	J81	2002-07	2014-01	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	73,241
Espace (LCV)	J81	2002-07	EOP	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	4
Grand Espace	J81	2002-07	EOP	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	4,168
Laguna	X74	2000-12	2007-09	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	149,015
Megane	X64	1997-01	2002-10	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	11,921
Scenic	J64	1997-01	2003-06	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	11,921
Vel Satis	X73	2001-09	2009-11	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault	147,056
3046						
Volvo						
V70	Y285	2007-05	2008-10	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	326
XC70	Y381	2007-05	2008-10	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	326
XC90	Y289	2002-04	2014-12	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	869
3049						
Cadillac						
CTS	GMX206	2008-01	EOP	20922901	Schrader Snap-in GEN4 type 433MHz GM	97
CTS	GMX226	2010-06	EOP	20922901	Schrader Snap-in GEN4 type 433MHz GM	227
Escalade	GMT926	2005-12	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,498
Escalade		2014-03	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	160

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Escalade	K2UL	2014-01	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	15
Escalade (LCV)	GMT926	2005-12	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	9
SRX	GMT166	2009-07	2015-12	25789964	Schrader Snap-in GEN4 type 433MHz GM	2,609
SRX	GMT265	2005-06	2009-02	25789964	Schrader Snap-in GEN4 type 433MHz GM	40
XTS	P1LL	2012-05	2018-03	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Chevrolet						
Aveo	G1JC,G1SC	2014-03	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	5,074
Aveo	G1SC	2010-11	2016-12	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,429
Captiva	C100	2006-06	2014-05	25789964	Schrader Snap-in GEN4 type 433MHz GM	14,448
Captiva			EOP	25789964	Schrader Snap-in GEN4 type 433MHz GM	4,992
Cobalt	G1LC	2013-2	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	15,946
Cruze	D1JC	2014-06	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	2,114
Cruze	D1WC	2014-06	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	3,268
Express (PC)	GMT610	2002-07	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	2
Malibu	V300	2010-07	2011-06	20922901	Schrader Snap-in GEN4 type 433MHz GM	908
Malibu		2011-07	2014-06	22853740	Schrader Snap-in GEN4 type 433MHz GM	164
Matiz	M100	2014-06	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,764
Orlando	J309	2010-09	2017-12	22853740	Schrader Snap-in GEN4 type 433MHz GM	5,904
Spark	M1JC	2009-07	2015-06	22853740	Schrader Snap-in GEN4 type 433MHz GM	7,001
Suburban	GMT931	2006-03	2008-07	22853740	Schrader Snap-in GEN4 type 433MHz GM	5
Trax	G1UC	2012-03	2017-12	22853740	Schrader Snap-in GEN4 type 433MHz GM	31,132
Daewoo						
Gentra	J200	2013-8	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	20,623
Nexia	T-CAR	2014-06	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	17,021
Nexia	T	2014-03	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	5,168
GMC						
Sierra	K2XG	2013-04	2019-06	22853740	Schrader Snap-in GEN4 type 433MHz GM	10
Yukon	GMT922	2005-12	2013-12	22853740	Schrader Snap-in GEN4 type 433MHz GM	275
Yukon	K2UG	2014-03	EOP	22853740	Schrader Snap-in GEN4 type 433MHz GM	20
Hummer						
H3	GMT345	2005-03	2012-01	25789964	Schrader Snap-in GEN4 type 433MHz GM	1
Opel						
Antara	C105	2006-08	2010-11	25789964	Schrader Snap-in GEN4 type 433MHz GM	775
Antara		2010-11	2017-05	22853740	Schrader Snap-in GEN4 type 433MHz GM	710
Mokka	G1UO	2012-06	2015-08	22853740	Schrader Snap-in GEN4 type 433MHz GM	52,383
3053						
Cadillac						
STS	GMX295	2005-06	2011-04	25758221	Schrader Clamp-in Gen J 433MHz GM	10
XLR	GMX215	2003-05	2009-04	25758221	Schrader Clamp-in Gen J 433MHz GM	9
Chevrolet						
Corvette	GMX245	2004-07	2010-01	25758221	Schrader Clamp-in Gen J 433MHz GM	1,698
3054						
Cadillac						
ATS	A1BL	2014-07	2018-06	20925925	Schrader Clamp-in Gen J 433MHz GM	9
ATS	A1SL	2012-07	2018-03	20925925	Schrader Clamp-in Gen J 433MHz GM	297
CTS	A1LL	2013-09	2018-03	20925925	Schrader Clamp-in Gen J 433MHz GM	175

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Chevrolet						
Camaro	GMX521	2010-11	EOP	20925925	Schrader Clamp-in Gen J 433MHz GM	601
Corvette	GMX245	2010-02	2013-01	20925925	Schrader Clamp-in Gen J 433MHz GM	954
3055						
Cadillac						
CTS	GMX322	2006-01	2007-06	25774007	Schrader Clamp-in Gen J 433MHz GM	416
Chevrolet						
Trailblazer (LCV)	GMT360	2001-01	EOP	25774007	Schrader Clamp-in Gen J 433MHz GM	4
3056						
Hyundai						
Veloster	FS	2011-02	EOP	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	1,843
3058						
Lotus						
Elise	Monza	2008-01	EOP	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	592
Evora	Eagle	2010-01	EOP	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	323
Exige	Monza	2008-01	EOP	12825085	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	491
3059						
Hyundai						
i10	IA	2013-11	EOP	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	82,551
Kia						
Soul	PS	2013-11	EOP	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	10,838
Soul (LCV)	PS	2013-10	EOP	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	7
3060						
Hyundai						
i20	GB	2014-01	EOP	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	2,565
i20	GB,IB	2014-11	EOP	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	774
i20 (LCV)	GB	2014-11	EOP	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	1
3062						
Chevrolet						
Malibu	V300	2014-07	2015-06	13581561	Schrader Snap-in GEN4 type 433MHz GM	164
Opel						
Adam	GM 4403	2014-08	2015-08	13581561	Schrader Snap-in GEN4 type 433MHz GM	22,337
Corsa	GM 4530	2014-11	2015-02	13581561	Schrader Snap-in GEN4 type 433MHz GM	1,005
Meriva	GM S4470	2014-08	EOP	13581561	Schrader Snap-in GEN4 type 433MHz GM	2,532
Meriva (LCV)	GM S4470	2014-06	EOP	13581561	Schrader Snap-in GEN4 type 433MHz GM	24
3064						
Subaru						
C-Concept	VL9	2014-6	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	4,250
Forester	FM5	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,361
Forester (LCV)	FM5	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	13
Impreza	MF1	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	3,011
Impreza	ZR1	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	165
Impreza (LCV)	MF1	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2
Justy	D71A	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1
Legacy	04AL	2014-10	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	262
Legacy	EZ5	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,553

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Outback	04AL	2014-11	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25
Outback	BF4	2014-9	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	472
Outback	EZ5	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	3,832
Trezia	217A	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	604
Tribeca	00X	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	5
XV	MF1	2014-01	EOP	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,411
3068						
Ssangyong						
Korando	C200/AS11	2013-08	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	5
Korando C	C200/AS11	2013-08	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	437
Korando C (LCV)	C200/AS11	2013-08	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2
Korando Sports	Q150	2014-11	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14
Nomad	Q150	2014-2	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	45
Rexton	Y200	2014-05	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	199
Rexton (LCV)	Y200	2014-05	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	17
Rexton SC	Y200	2014-05	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1
Rodius	A100	2014-05	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	169
Rodius (LCV)	A100	2014-05	EOP	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1
4001						
Alfa Romeo						
8C Competizione	920	2006-12	2010-12	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	96
Aston Martin						
Vanquish	AM310	2012-06	EOP	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	130
Audi						
A6 Allroad	AU566	2000-03	2006-05	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	104
A8	AU631	1999-09	2010-12	4D0 907 275 C	Beru-Huf Clamp-in Separate valve G1.2 433MHz VW Group	10,098
Ferrari						
F430	F131	2004-09	2007-06	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	35
F599 GTB	F141	2004-03	2012-06	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	73
Maserati						
GT Coupe	M145	2007-04	2009-07	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	178
Quattroporte	M139	2003-12	2012-10	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	718
Maybach						
57/62	W240	2002-10	2012-12	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	59
Mercedes-Benz						
CL	C215	1998-06	2006-02	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	200
CLS	C219	2004-09	2005-01	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	333
E-Class	W210	2001-11	2005-01	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	666
S-Class	W220	1998-05	2005-04	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	999
SL	R230	2001-06	2005-05	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	999
SLR	C199	2003-12	2007-06	A 005 542 23 18	Beru-Huf Clamp-in Separate valve G1.2 433MHz Daimler	626
Porsche						
911	997	2004-06	2008-06	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,938
Boxster	987	2004-10	2008-10	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	1,615
Cayman	987	2005-09	2008-12	997 606 021 00	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	959
Volkswagen						

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Phaeton	VW611	2001-12	2007-06	24 88 87	Beru-Huf Clamp-in Separate valve G2.2 433MHz Fiat Group	2,579
4002						
BMW						
3-Series	E46	1997-05	2004-12	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	3,343
5-Series	E39	1998-09	2003-07	36 11 8 378 682	Beru-Huf Clamp-in Separate valve G1.2 433MHz BMW	2,006
4003						
Land Rover						
Range Rover (LCV)	L322	2002-03	2003-02	YDB 0000 60	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Land Rover	36
4005						
Ferrari						
Enzo	Enzo	2003-01	2004-12	224551	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz Ferrari	109
Volkswagen						
Touareg	VW516	2002-10	2007-01	7L0 907 275 B	Beru-Huf Clamp-in Separate valve G1.2 plus 433MHz VW/Porsche	3,869
4007						
Alpina						
Alpina 3	E90	2007-03	2009-09	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	107
Alpina 6	E63	2006-03	EOP	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	3
BMW						
6-Series	E63	2006-03	2010-12	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	668
X5	E70	2006-10	2010-09	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	5,015
X6	E71	2007-12	2011-10	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	668
Z4	E89	2009-05	2010-08	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	33
Mini						
Clubman	R55	2007-08	2009-09	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	69
Rolls-Royce						
Phantom	RR01	2007-09	2011-12	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	124
Phantom Drophead Coupe	RR02	2007-04	2011-12	36 23 6 798 726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	124
4009						
Aston Martin						
Rapide	VH400	2010-01	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	92
V12 Zagato	Zagato	2012-09	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5
V8 Vantage	AM305	2005-07	2014-06	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	801
Virage	AM803	2011-05	2017-08	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1
Audi						
A4	AU461/AU471	2001-01	2007-10	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,365
A4 Cabrio	AU465/AU475	2004-11	2009-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	672
A6	AU561	2004-03	2009-06	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	673
A6		2009-06	2011-08	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	673
A6	AU571	2011-01	2017-12	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	15,353
A6 Allroad	AU566	2006-05	2009-06	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	182
A6 Allroad		2009-06	2011-12	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	193
A6 Allroad	AU572/4	2012-01	2019-09	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	625
A8	AU641	2009-11	2016-09	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,512
Q7	AU716	2005-09	2009-06	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,365
Q7		2009-06	2014-05	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,165
R8	AU714	2006-10	2009-06	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	672

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
R8	AU714	2009-06	2015-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,078
Bentley						
Azure	BY824	2006-06	2010-01	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6
Azure	BY835	2013-10	2020-10	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32
Continental Flying Spur	BY611	2005-03	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	17
Continental Flying Spur	BY621	2012-12	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,051
Continental GT	BY624	2005-06	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	7,489
Continental GTC	BY615	2006-05	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,880
Continental GTC	BY625	2011-11	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,125
Mulsanne	BY831	2009-09	2018-04	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,488
Ferrari						
California	F149	2008-07	2014-10	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	3,607
F12	F152	2012-01	2018-03	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	2,534
F430	F131	2007-07	2009-12	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	34
F458	F142	2009-09	2015-10	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	7,686
FF	F151	2011-06	2019-02	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,156
Lamborghini						
Aventador	LB834	2011-05	2019-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	886
Gallardo	LB714	2007-01	2010-01	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	682
Gallardo		2010-02	2013-05	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	986
Gallardo	LB724	2013-06	2021-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	94
Murcielago	LB824	2011-01	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	6
Maserati						
GranCabrio	M147	2009-09	2015-06	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	105
GT Coupe	M145	2009-07	2013-12	997 606 021 20	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	497
Porsche						
911	991	2011-09	2019-08	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	22,714
911	997	2008-07	2012-10	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,170
918 Spyder	918	2013-09	2014-12	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4
Boxster	981	2012-03	2019-04	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,551
Boxster	987	2008-07	2012-01	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,635
Cayenne	E2	2007-02	2010-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,228
Cayenne		2010-04	2017-01	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32,494
Cayenne (LCV)	E2	2010-03	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11
Cayman	981	2013-05	2020-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,000
Cayman	987	2009-01	2013-04	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,706
Panamera	970	2009-09	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	13,409
Volkswagen						
Phaeton	VW611	2007-06	2010-01	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,577
Phaeton		2010-01	2016-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,925
Touareg	VW516	2007-01	2010-03	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3,869
Touareg	VW526	2010-03	2014-02	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,120
Touareg (LCV)	VW526	2010-03	EOP	7PP 907 275 F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2
4010						
Alpina						
Alpina 3	E90	2009-09	2012-12	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	30

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Alpina 5	F10	2010-01	2017-10	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	194
Alpina 6	F06	2014-03	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2
Alpina 6	F12	2010-12	2018-10	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26
Alpina 7	F01	2010-09	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	16
BMW						
5-Series	F10	2010-01	2014-02	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	46,950
5-Series GT	F07	2009-09	2014-02	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,415
6-Series	F12	2010-12	2018-10	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,952
6-Series Gran Coupe	F06	2012-03	2019-02	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,843
7-Series	F01	2014-06	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,388
X1	E84	2009-09	2014-02	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	26,608
X3	F25	2010-09	2017-06	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	24,867
X3 (LCV)	F25	2014-06	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	6
X5	E70	2010-03	2013-06	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	11,159
Z4	E89	2010-09	2016-09	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,549
Mini						
Clubman	R55	2009-08	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,076
Clubman (LCV)	R55	2014-06	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	9
Clubvan	R55	2012-07	2015-06	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	157
Countryman	R60	2010-08	2017-12	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	21,364
Countryman (LCV)	R60	2014-06	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3
Coupe	R58	2011-07	2015-08	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	972
Paceman	R61	2012-11	2018-06	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	3,455
Roadster	R59	2011-12	2015-08	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,196
Rolls-Royce						
Ghost	RR04	2009-12	2019-11	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	88
Phantom	RR01	2003-02	2016-09	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	18
Phantom Coupe	RR02	2014-06	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	12
Phantom Drophed Coupe	RR02	2012-01	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	138
Wraith	RR04	2013-8	EOP	36 10 6 856 227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	401
4011						
Volkswagen						
Passat	VW471	2010-12	2013-09	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	13,346
Passat CC	VW464	2008-03	2014-09	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	540
Tiguan	VW316	2007-08	2014-02	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	13,456
Tiguan (LCV)	VW316	2007-08	EOP	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	7
Touran (LCV)	VW368	2010-07	EOP	3AA 907 275 D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	26
4012						
Audi						
A3 Sportback	AU370	2012-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,149
A3 Sportback (LCV)	AU370	2012-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A4 (LCV)	AU481	2014-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11
A4 Allroad	AU486	2009-03	2015-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	484
A5	AU484	2006-12	2015-06	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	837
A5 Cabrio	AU485	2008-11	2015-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,524
A5 Sportback	AU483	2009-07	2016-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,467

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
A5 Sportback (LCV)	AU483	2014-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A6 (LCV)	AU571	2011-01	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
A7	AU573	2010-09	2017-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	716
Q3	AU316	2011-07	2018-03	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,993
Q3 (LCV)	AU316	2011-07	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Q5	AU416	2008-09	2015-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,196
Q5 (LCV)	AU416	2008-09	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Q7	AU726	2014-06	2021-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
TT	AU334	2014-02	2020-10	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	789
Porsche						
Macan	PO416	2013-05	2020-07	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	18,307
Skoda						
Citigo	SK120	2011-10	2018-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,560
Fabia	SK250	2014-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,909
Fabia	SK260	2013-11	2019-04	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	480
Fabia Van	SK250	2014-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	33
Fabia Van	SK260	2013-11	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Octavia	SK371	2012-11	2019-06	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,761
Octavia (LCV)	SK371	2012-11	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Rapid	SK251/1	2012-09	2020-04	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,712
Rapid Spaceback	SK253/1	2013-10	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,784
Roomster (LCV)	SK258	2006-04	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4
Yeti	SK316	2009-06	2015-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,051
Yeti (LCV)	SK316	2009-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Volkswagen						
Amarok	VN817	2009-11	2017-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,727
Caravelle	VN750	2003-12	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,982
Eos	VW465	2006-02	2015-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	477
Golf	VW360	2014-05	2016-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,280
Golf	VW370	2012-08	2018-06	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	61,432
Golf (LCV)	VW370	2012-08	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29
Golf Plus	VW379	2014-02	2019-01	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,167
Golf Plus (LCV)	VW379	2014-02	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13
Golf Sportsvan	VW379	2014-3	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	841
Golf Sportsvan (LCV)	VW379	2014-4	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3
Golf SV	VW379	2014-03	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	168
Jetta	VW361	2010-07	2016-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,848
New Beetle	VW324	2011-08	2017-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,158
New Beetle Convertible	VW325	2012-09	2017-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,716
Passat	VW471	2013-09	2014-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,334
Passat CC	VW464	2014-09	2015-06	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,181
Scirocco	VW364	2008-06	2016-06	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,374
Scirocco (LCV)	VW364	2008-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
Sharan	VW428	2010-06	2017-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,181
Sharan (LCV)	VW428	2010-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2
Tiguan	VW316	2014-02	2014-12	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,139

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Touareg	VW526	2014-03	2017-09	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,106
Transporter	VN750	2003-03	2017-03	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,754
Transporter Shuttle	VN750	2014-06	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8
Up!	VW120	2011-08	2018-07	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,323
Up! (LCV)	VW120	2011-08	EOP	5Q0 907 275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
4015						
Lancia						
Flavia	JS27	2010-10	EOP	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	1,943
4016						
Jeep						
B-CUV	520	2014-10	EOP	Info not available	Conti Snap-in TG1D 433MHz Chrysler	96
Lancia						
Flavia	UF	2014-02	EOP	Info not available	Conti Snap-in TG1D 433MHz Chrysler	203
4019						
Land Rover						
Freelander	L550	2014-07	EOP	LR058023	Conti Clamp-in TG1C 433MHz Ford	46
4021						
Ford						
Galaxy	CD340	2006-01	2014-12	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	5,965
Mondeo	CD345	2007-01	EOP	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	16,422
S-MAX	CD340	2006-02	EOP	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	6,466
S-Max (LCV)	CD340	2006-02	EOP	8G92 1A189-KB	Conti Clamp-in TG1C 433MHz Ford	14
4023						
Jaguar						
XF	X250	2007-11	EOP	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	26,608
XJ	X350	2005-10	EOP	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	2,024
XK	X150	2006-01	EOP	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	1,739
X-Type	X400	2007-01	EOP	C2Z15016	Conti Clamp-in TG1B 433MHz Ford	1,349
Land Rover						
Discovery (LCV)	L319	2004-07	2009-09	LR031712	Conti Clamp-in TG1B 433MHz Ford	47
Range Rover (LCV)	L322	2005-01	2009-12	LR031712	Conti Clamp-in TG1B 433MHz Ford	24
Range Rover Evoque	L538	2014-06	EOP	LR031712	Conti Clamp-in TG1B 433MHz Ford	31,116
4025						
Hyundai						
i40	VF	2011-04	2014-03	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	3,410
i40 (LCV)	VF	2011-04	2014-03	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	3
4026						
Hyundai						
i10	IA,PA	2007-10	EOP	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	761
i10 (LCV)	PA	2014-03	EOP	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	6
i30	FD	2007-10	2012-06	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,745
4027						
Hyundai						
Accent	RB	2014-03	EOP	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	7,798
i20	PB	2008-08	2014-06	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	19,502
ix20	JC	2010-09	2013-09	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	15,326

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
ix20 (LCV)	JC	2010-09	2013-09	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	6
Solaris	RB	2014-03	EOP	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	87,315
Kia						
Optima	TF	2011-09	2013-08	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	2,777
Sorento	XM	2009-05	2012-09	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	8,338
Venga (LCV)	YN	2010-02	2014-04	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	9
4028						
Mazda						
2	J64F	2007-12	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	9,535
3	J68C	2009-07	2013-03	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	1,189
5	J74G	2010-07	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	3,491
6	J61A	2007-08	2012-08	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	396
6	J71E	2013-03	2018-09	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	16,883
6 (LCV)	J71E	2014-06	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	4
CX-5	J53C	2011-11	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	31,180
CX-5 (LCV)	J53C	2011-11	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	7
CX-7	J31H	2009-06	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	178
CX-9	J50C	2010-08	EOP	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	124
MX-5	J04C	2010-03	2015-03	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	2,599
4029						
Peugeot						
4008	J3	2014-06	EOP	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	1,834
4008 (LCV)	J3	2014-06	EOP	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	3
iOn	S3	2014-06	EOP	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	408
iOn (LCV)	S3	2014-06	EOP	Info not available	Conti Clamp-in TG1C 433MHz Mitsubishi	10
4030						
Nissan						
Atleon	F91G	2014-01	EOP	(blank)	Conti Clamp-in TG1C 433MHz Nissan	158
Cabstar	F91A	2014-06	EOP	(blank)	Conti Clamp-in TG1C 433MHz Nissan	260
Cabstar E	F91A	2014-06	EOP	(blank)	Conti Clamp-in TG1C 433MHz Nissan	81
NV300	X82	2014-9	EOP	(blank)	Conti Clamp-in TG1C 433MHz Nissan	58
NV300 Combi	X82	2014-9	EOP	(blank)	Conti Clamp-in TG1C 433MHz Nissan	10
4031						
Citroen						
C4	B5	2004-11	2008-06	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	3,356
C5	X3/X40	2004-08	2007-12	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	105,385
C5	X7	2008-01	2013-09	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	79,565
C6	X6	2005-09	2012-12	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1,678
C8	V3	2005-09	2014-06	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	12,677
Fiat						
Ulysse	V1	2001-01	2010-10	9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	897
Lancia						
Thema	LX	2011-01	EOP	9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	6,607
Peugeot						
1007	A08	2014-03	EOP	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	1
207	A7	2005-11	2013-09	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	4,777

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
307	T5	2003-11	2006-12	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	94,727
407	D2	2004-01	2006-02	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	268,729
508	W2	2010-11	2013-09	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	97,327
508 RXH	W24	2012-01	2013-09	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	45
607	Z8	2004-10	2009-03	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	11,420
807	V2	2004-10	EOP	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	15,628
4032						
Nissan						
Almera	LB1A	2013-5	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	43,114
C-Hatch	B12L	2014-10	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	2,580
Note	J02C	2013-08	2017-03	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	29,152
Note (LCV)	J02C	2012-03	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	13
NV200	X11M	2014-04	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,050
NV200 Combi	X11M	2014-04	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	396
Qashqai	P32S	2013-12	2019-12	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	201,622
Qashqai (LCV)	P32S	2013-12	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	232
Sentra	L12F	2014-8	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	2,040
Teana	L42L	2014-01	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	7,126
X-Trail	P32R	2013-11	2019-12	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	17,548
X-Trail (LCV)	P32R	2013-11	EOP	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	90
4034						
Renault						
Espace (LCV)	JFC	2014-07	EOP	Info not available	Conti Snap-in TG1D 433MHz Renault	17
4035						
Renault						
Fluence	L38	2009-10	2015-06	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	16,784
Laguna	X91	2007-10	2015-03	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	51,944
Laguna (LCV)	X91	2007-06	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	13
Laguna Coupe	D91	2008-07	2014-06	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	7,607
Latitude	L43	2010-09	2015-12	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	1,734
Megane	B32	2009-11	2015-12	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	113
Megane	B32,X95	2011-05	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	6,186
Megane	X95	2008-11	2015-09	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	95,976
Megane Van	X95	2014-06	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,308
Scenic	J95	2009-01	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	57,513
Scenic (LCV)	J95	2009-02	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	38
Zoe	X10	2012-09	2019-03	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,471
Zoe (LCV)	X10	2013-06	EOP	40 70 004 35 R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3
4036						
Renault						
Megane	X84	2002-11	2008-10	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	59,606
Megane Van	X84	2014-03	EOP	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	5
Scenic	J95	2003-06	2007-10	40 70 055 78 R	Conti Clamp-in TG1B Siemens VDO 433MHz Renault	71,527
4037						
Volkswagen						
New Beetle	VW314	2006-01	2010-07	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	1,934

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Passat	VW451	2005-03	2010-11	1K0 907 253 C	Conti Clamp-in TG1B Siemens VDO 433MHz VW	22,570
4038						
Volkswagen						
Crafter	VN830	2006-04	2017-09	A 002 540 95 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	4,777
Crafter Combi	VN830	2014-06	EOP	A 002 540 95 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	21
4040						
Mercedes-Benz						
CLS	C219	2005-01	2009-07	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	399
GL-Class	X164	2006-01	2009-06	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	66
R-Class	V251	2005-06	2009-06	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	499
S-Class	W221	2005-05	2009-06	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	3,330
SL	R230	2005-02	2009-07	A 002 540 80 17	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler	1,332
4041						
Volvo						
C30	Y279	2006-09	2012-12	31302096	Conti Clamp-in TG1C 433MHz Volvo	257
V50	Y280	2003-11	2012-05	31302096	Conti Clamp-in TG1C 433MHz Volvo	360
V60	Y352	2010-09	2014-06	31302096	Conti Clamp-in TG1C 433MHz Volvo	327
XC60	Y413	2008-05	2014-06	31302096	Conti Clamp-in TG1C 433MHz Volvo	459
XC70	Y381	2007-02	2014-06	31302096	Conti Clamp-in TG1C 433MHz Volvo	268
4042						
Volvo						
V70	Y285	2008-01	2014-06	31302097	Conti Clamp-in TG1C 433MHz Volvo	318
4043						
Alpina						
Alpina 3	F30	2013-01	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	270
Alpina 3	F32	2013-04	2017-06	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	159
Alpina 4	F32	2014-03	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	55
BMW						
1-Series	F20	2011-07	2018-12	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	53,893
1-Series (LCV)	F20	2014-06	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	21
2-Series	F22	2013-11	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	14,566
2-Series Active Tourer	F45	2014-07	2021-06	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	5,502
3-Series	F30	2011-11	2018-10	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	63,760
3-Series (LCV)	F30	2014-05	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	3
3-Series GT	F34	2013-03	2020-01	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	11,262
4-Series	F32	2013-10	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	45,277
4-Series Gran Coupe	F36	2014-7	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	6,140
i3	I01	2013-09	2020-04	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	10,186
i8	I12	2014-01	2020-04	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	674
X4	F26	2014-04	2020-03	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	8,237
X5	F15	2013-07	2020-03	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	43,537
X5 (LCV)	F15	2014-06	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	8
Mini						
Mini	F56	2013-12	2021-06	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	60,820
Mini	R56	2014-06	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	10,338
Mini (LCV)	F56	2014-01	EOP	3610 6856 209	Conti Clamp-in TG1C 433MHz BMW	9

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
4044						
Toyota						
RAV4 (LCV)	120L	2005-11	2012-12	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	230
4045						
Lexus						
C-CUV	600A	2014-11	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
CT	080A	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,484
ES	980L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,717
GS	920L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,169
GX	837L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	107
IS	030L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	967
IS	400A	2013-7	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,428
LF-A	973L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
LS	250L	2014-01	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	537
LX	220L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	159
NX	600A	2014-03	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,347
RX	640L	2014-06	EOP	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	681
Subaru						
BRZ	E88	2014-01	EOP	28103-CA101	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	750
Toyota						
Alphard	480L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18
Auris	130A	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	78,919
Auris	130L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Auris (LCV)	130A	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	13
Avalon	770N	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Avenis	312N	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4
Avenis	445L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	18,243
Avenis (LCV)	445L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Camry	050A	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,378
Camry	045L	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Corolla	140A	2014-01	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	199
Corolla	150A	2014-10	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	139
Corolla	366A	2013-9	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	49,545
Corolla	150L,252L	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	368
Corolla	466A	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	19,569
Dyna	Dutro(2)	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3
Dyna	U300-500	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Dyna	U600/C600	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	82
Dyna	131N	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	609
GT 86	E88	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,094
Hiace	550N	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	36
Highlander	440A	2014-10	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	35
Highlander	397L	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Hilux	669L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,785
IQ	630L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,265
Land Cruiser	215L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,091

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Land Cruiser	611L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	112
Land Cruiser (LCV)	215L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	120
Land Cruiser Prado	611L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	957
Land Cruiser V8	215L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	45
Prius	590L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,273
Prius (LCV)	590L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius Plus	030A	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	405
RAV4	410A	2013-01	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	9,837
Sienna	580L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10
Tundra	180L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Tundra	480A/180L	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
Urban Cruiser	260L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	396
Venza	470L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	285
Verso	151L,595L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	21
Verso	595L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,073
Verso (LCV)	595L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	37
Verso-S	770L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,008
Verso-S (LCV)	770L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Yaris	020L	2014-03	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2
Yaris	850L	2014-06	EOP	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	98,805
4047						
Nissan						
Juke	P12C	2010-05	2015-09	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	46,985
Juke (LCV)	P12C	2010-05	EOP	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	21
Leaf	B12G	2010-10	2017-09	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	5,426
4052						
Hyundai						
Equus	VI	2014-03	EOP	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	544
Kia						
Quoris	KH	2013-1	EOP	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	491
Rio (LCV)	QB	2014-03	EOP	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	6
4053						
Hyundai						
Elantra	HD	2014-03	EOP	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10
Elantra	MD	2014-03	EOP	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	6,222
Kia						
Rio	UB	2012-11	EOP	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	25,003
Rio (LCV)	UB	2000-01	EOP	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	26
4054						
Alfa Romeo						
159	939	2005-07	2011-11	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	354
Brera	946	2005-11	2010-12	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	35
MiTo	955	2008-06	2013-07	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,114
Spider	946	2006-06	2010-12	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	35
Chrysler						
Delta	844	2013-02	EOP	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	8

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Fiat						
Bravo	198	2007-01	2014-09	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	933
Punto	199	2005-09	2015-03	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	48,945
Lancia						
Delta	844	2008-04	EOP	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	4,745
4056						
Kia						
Rio	QB	2000-01	EOP	52933-3J000	Lear Clamp-in Variable Angle ver 1 433MHz HKMC	86,591
4057						
Hyundai						
Santa Fe	CM	2005-12	EOP	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	13
4058						
Tesla						
Model S	Model S	2013-5	EOP		Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	9,623
4059						
Hyundai						
Genesis	DH	2014-01	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	886
Genesis Coupe	BK	2014-03	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	222
i30	GD	2011-11	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	39,132
i30 (LCV)	GD	2011-10	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	6
Santa Fe	DM	2012-04	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	9,254
Santa Fe (LCV)	DM	2014-03	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	10
Kia						
Carens	RP	2012-12	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	2,037
Ceed	JD	2012-03	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	43,836
Ceed (LCV)	JD	2014-03	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	5
New Carens	RP	2013-06	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	18
Picanto	TA	2014-06	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	31,530
Picanto (LCV)	TA	2014-06	EOP	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	11
4060						
Hyundai						
ix20	JC	2013-05	EOP	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	15,629
Kia						
Cadenza	VG	2013-10	EOP	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	51
Optima	TF	2013-08	EOP	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	2,508
Sorento	UM	2014-11	EOP	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	4
Sorento (LCV)	XM	2014-03	EOP	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	18
4061						
Hyundai						
Grandeur	HG	2014-03	EOP	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	208
4062						
Hyundai						
iX35	LM	2014-03	EOP	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,555
iX35 (LCV)	LM	2014-03	EOP	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	12
Kia						
Sportage	SL	2010-01	EOP	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	53,183

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Sportage (LCV)	SL	2014-03	EOP	52933-2S410	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	14
4063						
Kia						
Cerato	YD	2013-3	EOP	52933-A7100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	11,670
4064						
Honda						
Civic	2HC	2014-06	EOP	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	31,090
Jazz	2AP,2HQ	2014-06	EOP	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	19,507
Jazz	2WF	2014-9	EOP	42753-SNA-A83	TRW Clamp-in Fixed Angle ver 2 433MHz Honda	1,875
4065						
Fiat						
Sedici	YY2	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	164
Opel						
Agila	H0310	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	742
Suzuki						
Alto	YC5	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	14,865
Alto Van	YC5	2014-03	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1
Jimny	YR6,YR7	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	83
Jimny	YR7	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	576
Jimny (LCV)	YR7	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	40
Splash	YV1	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	781
Splash	YV1,YV4	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2
Splash	YV4	2013-9	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	1,269
Swift	YP6	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	7,691
Swift	YP6,YP7	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	21,259
Swift (LCV)	YP6	2014-06	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	7
SX4	YY1,YY3	2013-08	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	784
SX4 S-Cross	YAA	2013-11	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	48,952
SX4 S-Cross (LCV)	YAA	2013-11	EOP	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	38
4066						
Jaguar						
F-Type	X152	2014-03	EOP	Unknown	Conti Clamp-in TG1C 433MHz JLR	4,523
Land Rover						
Range Rover Sport	L494	2014-06	EOP	Unknown	Conti Clamp-in TG1C 433MHz JLR	1,775
Range Rover Sport (LCV)	L494	2014-06	EOP	Unknown	Conti Clamp-in TG1C 433MHz JLR	12
4068						
Jeep						
Cherokee (LCV)	KL	2014-06	EOP	Info not available	TRW Clamp-in Variable Angle ver 1 433MHz Chrysler	3
4070						
Volvo						
V40	Y555	2014-03	EOP	31341171	Conti Clamp-in TG1C 433MHz Volvo	50,018
V40 (LCV)	Y555	2014-07	EOP	31341171	Conti Clamp-in TG1C 433MHz Volvo	10
V40 XC	Y555	2014-03	EOP	31341171	Conti Clamp-in TG1C 433MHz Volvo	6,052
4072						
Honda						
Accord	2GB	2014-06	EOP	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	3,155

Schrader Part Number (NEW)	Car Model Code	Start of application	End of application	OE Sensor reference	Sensor description	Direct TPMS car park in Market in 2014
Accord	QE	2014-06	EOP	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	1,138
4073						
Citroen						
C4 Aircross	J4	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	662
C4 Aircross (LCV)	J4	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5
Mitsubishi						
ASX	ZC	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3,121
ASX (LCV)	ZC	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5
i-MiEV	TQ	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	489
L200	4P00,CR	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	93
L200	CR	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,153
Lancer	GS41	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	4,895
Outlander	GS45X	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	10
Outlander	GS45X,RE	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	42
Outlander	RE	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3,363
Outlander (LCV)	RE	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	3
Pajero	BK	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	686
Pajero (LCV)	BK	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	62
Spacestar	EL	2014-06	EOP	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	9,369
4077						
Nissan						
Micra	B02A	2010-03	2016-12	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	25,154
Micra (LCV)	B02A	2010-03	EOP	40700-3NH0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	2
4078						
Hyundai						
i40	VF	2014-04	EOP	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	10,226

Euroguide -Service Kits Look Up

Service Kits Look Up: The application sensor list applied to a service kit is a list detailing which sensors can be serviced with that particular service kit. The number besides the code represents the quantity included in package (for example 5001-10 means a package containing 10 Service kits)

- 1/ The first column "**Service Kits Part Nr./ Schrader Part Number (NEW)**" lists each service kit and identifies the sensors matching with the selected service kit (red references)
- 2/ The second column titled "**Service Kit Description**" shows the description of the selected service kit.
- 3/ The remaining column details the After Market "**Sensor Description**" of the sensor that can be serviced with the selected service kit.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated.
For further information: tpmseuroshop.com or aftermarket@schrader.co.uk

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
5002-10		
3040	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Renault
3043	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Conical Seal 433MHZ Renault
5003-10		
3004	Service Kit for SEL Clamp-in Gen2 type 433MHZ PSA PWM (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA
5004-10		
3026	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3031	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3037	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Nissan
3046	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Volvo
3058	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
5005-10		
4036	Service Kit for Conti TG1B Renault (Pack of 10)	Conti Clamp-in TG1B Siemens VDO 433MHZ Renault
5006-10		
4031	Service Kit for Conti TG1B PSA Ford (Pack of 10)	Conti Clamp-in TG1B Siemens VDO 433MHZ PSA
5007-10		
4037	Service Kit for Conti TG1B black nut VW (Pack of 10)	Conti Clamp-in TG1B Siemens VDO 433MHZ VW
5014		
4026	Service Kit for Conti TG1B HKMC	Conti Clamp-in TG1B 433MHZ HKMC
5015		
4038	Service Kit for Conti TG1B Daimler	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHZ Daimler
5016-10		
3039	Service Kit for SEL Gen 3.1 Nissan (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHZ Nissan

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
5017-10		
3011	Service Kit for SEL Gen-Alpha Aluminium rims Daimler Chrysler WAL (Pack of 10)	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
5018		
4035	Service Kit for Conti TG1C Renault	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
5019-10		
3015	Service Kit for SEL Gen-Alpha Steel rims Daimler Chrysler WAL (Pack of 10)	Schrader Clamp-in Gen Alpha for Steel Rims 433MHz Daimler
5020		
4019	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4041	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Volvo
4065	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Suzuki
4021	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4070	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Volvo
4072	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Honda
4073	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Mitsubishi
5021		
4027	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
4059	Service Kit for Conti TG1C HKMC	Replaced by 4060
4060	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
5026-10		
3000	Valve for for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	Valve for for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
5027-10		
3053	Service Kit for SEL Gen-Alpha Chrysler WAL (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM
5028-10		
1200	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ USA
1210	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz programmable WAL EZ USA
3005	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford
3027	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Valve for for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
5029-10		
3008	Service Kit for SEL Gen-Alpha Chrysler FSK basic (Pack of 10)	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
5030-10		
3054	Service Kit for SEL Gen-J GM (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3055	Service Kit for SEL Gen-J GM (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM
5031-10		
2000	Valve for SEL EZ-sensor clamp-in - includes mounting screw (Pack of 10)	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ sensor Europe
3070	Valve for SEL EZ-sensor clamp-in - includes mounting screw (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
5032-10		
2000	Service Kit for SEL EZ-sensor clamp-in - without valve (Pack of 10)	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ sensor Europe
3070	Service Kit for SEL EZ-sensor clamp-in - without valve (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
2020	Service Kit for SEL EZ-sensor clamp-in - without valve (Pack of 10)	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ sensor Europe
5033-10		
3041	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 10deg angle 433MHz Daimler
8001		
3011	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
3015	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Steel Rims 433MHz Daimler
3008	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
8002-10		
4035	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
4032	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Renault
4041	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Volvo
4027	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz HKMC
4021	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Ford
4059	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Replaced by 4060
4060	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz HKMC
8003-10		
4019	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Ford
4065	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Suzuki
4028	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Mazda
4043	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz BMW
8004-10		
1200	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ USA
1210	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ USA
3000	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3027	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
8006-2000		
3041	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3070	HSS screw (Pack of 2000)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
3012	HSS screw (Pack of 2000)	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Renault T4
5037-10		
3013	Service Kit for SEL Gen Gamma GM (Pack of 10)	Schrader Clamp-in Gen Gamma 433MHz Daimler
5024-10		
1200	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ USA
1210	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ USA
3000	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford
3027	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
5038-10		
2020	Valve for SEL EZ-sensor clamp-in 2020 part - includes mounting screw (Pack of 10)	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ sensor Europe
5008		
4040	Service Kit for Conti TG1B Daimler	Conti Clamp-in TG1B_no RF link Siemens VDO 433MHz Daimler
5022		
4028	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz Mazda
5057		
4032	Service Kit for Conti TG1C Renault / Nissan	Conti Clamp-in TG1C 433MHz Renault
5058		
4043	Service Kit for Conti TG1C BMW / Mini	Conti Clamp-in TG1C 433MHz BMW